Work Order ID 59928 Page 1 Thursday, June 17, 2010 10:41:10 AM D3929-042 Item ID: Accept 两 Setup Start **Revision ID:** Stop Gusset Assembly Item Name: **Start Date:** 6/17/2010 **Cust Item ID: Required Date:** 6/24/2010 Req'd Qty: 6.00 **Customer:** Reference: Run Start Date: 10-4-11 Tooling: Process Plan: Approvals: Date: Stop QC: Date: _____ SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool # Plan Reject **Tool ID** Accept Reject Insp. :-Work Center ID Description **Run Hours** Qty Code Qty Number Stamp Draw Nbr **Revision Nbr** D3929 Α 100 0.00 B 10-6-17 Waterjet 0.00 Memo FLOW CNC Waterjet 1-Cut as per Dwg D3929 Dwg Rev: Prog Rev: 2-Deburr if necessary 110 QC2- Inspect parts off machine FAI/FAIB 0.00 B10-6-17

0.00

Memo

Quality Control

Dart A	erospace	Ltd
--------	----------	-----

W/O:		WORK ORDER CHANGES				· · · · · · · · · · · · · · · ·	
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						<u> </u>	
		·	<u>.</u> :		ļ <u>.</u>		
Dart No	·•	PAP #- Fault Category:	NCB: V	es No DC	١Δ٠	Date:	•

Resolution: _____ Disposition: _____ QA: N/C Closed: ____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B	Verification	Approval	Approval					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector				
í												

•		,										
Work Ord Thursday, June												Page 2
Item ID: Revision ID:	D3929-042	· •		Accept					Setup	Start Stop		
Item Name: Start Date: Required Date: Reference:	Gusset Assem 6/17/2010 : 6/24/2010	Start Qty: 6.00 Req'd Qty: 6.00	 		Cust Item I Customer:	D:				отор		
Approvals:	Process Pla	en:	Date:	Tooling: SPC (Y/N):		ate:			Run	Start Stop		
Sequence ID/ Work Center II 120 QC Quality Control	D	Operation Description QC8- Inspect parts - second Memo	and check	Set Up/ Run Hours 0.00 0.00	Tool ID	Tool#	Plan Code	Accept Qty	t Reje Qty		Reject Number	Insp. Stamp
140 Large Fab		Memo		0.00					y 10,	102/	17	(Fx)

Large Fab

Weld bushings D3907-1 as per dwg D3929

316L rod batch: 11/13328

150

QC9- Inspect visual per QSI004- Fusion Welds

0.00

(D) D) 10.06.16

Quality Control

0.00

Memo

Dart Aerospace L	td
------------------	----

W/O:				WORK OR	DER CHANG	ES				4
DATE	STEP		PROCE	DURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					t .				i	
					·					
							-			
Part No	:	1	PAR #:	Fault Category:	 	_ NCR : Yes	No DQ	A:	Date: _	
	R	esolution:		Disposition:		_ QA: N/C C	losed:		Date: _	

NCR:	į	WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B	Verification	Approval	Approva					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto				
						:						
		. •										
		· ·		ļ								

Work Orde Thursday, June												Page 3	
Item ID: Revision ID: Item Name: Start Date:	D3929-042 Gusset Asseml 6/17/2010	bly Start Qty: 6.00		Accept	Cust Item 1				Setup	Start Stop			
Required Date: Reference:	6/24/2010	Req'd Qty: 6.00	†		Customer:								
Approvals:	Process Pla	n:	Date:	Tooling:	Da	ite:	_		Run	Start			
	QC:		Date:	SPC (Y/N):	Da	ite:				Stop			
Sequence ID/ Work Center II 160 QC Quality Control)	Operation Description QC5- Inspect part compl Memo	eteness to step on W/O	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accept Qty	Qty		Reject Number	Insp. Stamp	
		Identify as per dwg & Sto	ock Location: <u>W</u> 4	0.00 S 介的)			A)				

Packaging

180

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Quality Control



Packaging

Memo

0.00 10-06-18

10/06/21 Af

W/O:		WORK ORDER C	HANGES	· #11 -/			;
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	·						•
						This is the second of the seco	
						·	
	:						
Part No.		PAR #· Fault Category:	NCR: Yes	No DO	Δ٠	Date:	•

Part No:		_PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approvai	Approvai			
DATE	STEP	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
		•									

Picklist Print

Thursday, June 17, 2010 10:41:13 AM

Work Order ID: 59928

Parent Item:

D3929-042

Parent Item Name: Gusset Assembly



57937

Start Date: 6/17/2010

Required Date: 6/24/2010

Page 1

Start Qty: 6.00

Required Qty: 6.00

Comments:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Date Issued Issue	Julia
M304S11GA	HIII 88811	Purchased	No			100	sf	146.8059	0.45	2.842105	3 8 10-6-17	
,				<u>Location</u> MAT	114488 114799	146	Qty .8059 .8059 128	Loc Code	<u>+</u>	14488		,
D3907-1 	RIM	Manufactured	No			130	Each	18.0000	2	12 W	10/06/17	٤
				<u>Location</u> WA		Loc	<u>Oty</u> 18	Loc Code				

18

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
			· -										
				·									
·			14-1-14-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1										
Part No	•	PAR #:	Fault Cate	jory:	NCR: Yes	No DQ	A:	Date:					
		esolution:											
NCR:		•	WORK ORDE	R NON-CONFORM	ANCE (NCF	R)							
DATE	STEP	Description of NC			VARITICATION : Approve				Approval				
DAIE	SIEP	Section A	Initial Action Descript Chief Eng Chief Eng		Sign & Date	Sect	ion C	Chief Eng	QC Inspector				
	<u> </u>					_	-						
					•								
•													

DART AEROSPACE LTD	Work Order:	59928
Description: Support Gusset	Part Number:	D3929-1
Inspection Dwg: D3929 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST


X	First Article	Prototype
---	---------------	-----------

Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
Dimension	roicianoc	Dimension	Accept	Reject	Inspection	Comments
Ø0.375	+0.006/-0.001	377	4			
0.500	+/-0.010	,500				
0.500	+/-0.010	· S08	2			
4.036	+/-0.010		3			, ,
4.382	+/-0.010	4.382	ጉ			
8.274	+/-0.010	8.074	L			
10.915	+/-0.010	१० ५१७	L			
1.000	+/-0.010	1.010	y			
11.198	+/-0.010	11.198	7			
0.500	+/-0.010	500).			
1.572	+/-0.010	. 474	>			
0.125	+/-0.010	1.574	Sy.			
					-	
			-			
· · · · · ·						
				-		
						
						-
		· · · · · · · · · · · · · · · · · · ·				
			`	" 	,	


Measured by:	B	Audited by:	Prototype Approval:	N/A
Date:	10-6-17	Date: 10/06/17	Date:	N/A

Rev	Date	Change		Revised by	Approved
Α	09.05.27	New Issue	P/O D3929-041/-042	KJ 👯	13/


Dait Aci	OSPACE	Liu							
W/O:			WO	RK ORDER CHANGES	3				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:		_ Date: _	
	Re	esolution:	Disposition	n:	QA: N/C Clo	sed:		Date: _	
NCR:		,	WORK ORDE	ER NON-CONFORMAN	ICE (NCR)			
DATE	STEP	Description of NC		В	Verifica	tion	Approvai	Approval	
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	C	Chief Eng	QC Inspector
									ę.
1		**************************************						-	
					i				



Dart Ae	rospace L	td							
W/O:			WO	RK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
									ı
									!
									1
									: 1
									ı
									i
	<u> </u>								!
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No DQA	\:	_ Date: _	1
	Res	olution:	Disposition	:	QA: N/C Cld	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMAN	ICE (NCR)		4	Ì
	T	Description of NC		Corrective Action Section		Verific	ation	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspecto
									ı



W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
									1 100 11191				
			· · ·						· · · · · · · · · · · · · · · · · · ·				
								:					
Part No		PAR #:			NCR	: Yes I	No DQ	A:	Date: _				
		solution:											
NCR:			WORK ORDI	ER NON-CONFOR	RMANCE	(NCR))						
DATE	0750	Description of NC	Corrective Action Se				Verifi	cation	Approvai	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Descript Chief Eng	ion	Sign & Date		ion C	Chief Eng	QC Inspector			
110				<u>:</u>									
•													
· · · · · · · · · · · · · · · · · · ·													
	i l		1				1		I	I			



W/O:		WORK ORDER CHANGES										
DATE	STEP	2	PROCEDURE CHANGE	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
								1				
				÷								

Part No:		_ PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:	·	Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification	Approval	Approval
			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		,			·			
					1			
 -		_						
		`						ļ
			, ,					